		General	
SPCC Type:	Drum Storage Area	SPCC Custodian:	
Capacity:	N/A	Phone No.:	542-2200
Fuel Type:	Varies, Used oil	Facility:	NADEP
Year Installed:		Building:	868
Type of Service:	<b>Temporary Storage</b>	Map & Grid No.:	6B, H-16
Condition:		Corrosion Protection:	N/A
Color:	N/A	Support:	N/A
Fuel Markings:	Adequate	Shape:	
Surrounding Surface:	Concrete	Material:	Concrete
	Seconda	ry Containment	
Type:	Concrete Curbing	Dike Drainage:	None
Condition:	New	Outfall:	Storm water drain
Lining:	None	Valve Locking:	N/A
Dim. (LxWxH):			
	Secui	rity / Lighting	
Lighting Adequacy:	Adequate	Piping:	N/A
SPCC Security:	Adequate	Pump Starter:	N/A
Potential for a spill to reach 1	navigable waters: HIGH		
	Notes & I	Recommendations	
FOR COMPLIANCE:			
	nce, ensure proper inspection of su	imp area prior to pumping.	

		General	
SPCC Type:	Drum Storage Area	SPCC Custodian:	
Capacity:	N/A	Phone No.:	542-2200
Fuel Type:	Varies, Used oil	Facility:	NADEP
Year Installed:		Building:	868
Type of Service:	Temporary Storage	Map & Grid No.:	6B, K-17
Condition:		Corrosion Protection:	N/A
Color:	N/A	Support:	N/A
Fuel Markings:	Inadequate	Shape:	
Surrounding Surface:	Concrete	Material:	Steel Housing
	Seconda	ary Containment	
Type:	None	Dike Drainage:	N/A
Condition:	N/A	Outfall:	N/A
Lining:	N/A	Valve Locking:	N/A
Dim. (LxWxH):			
	Secur	rity / Lighting	
Lighting Adequacy:	Inadequate	Piping:	N/A
SPCC Security:	Adequate	Pump Starter:	N/A
	· 11 · · · · · · · · · · · · · · · · ·		
Potential for a spill to reach	navigable waters: HIGH		

## FOR COMPLIANCE:

40 CFR 112: 1) Erect signage indicating type of oil stored;

2) Erect lighting such that a spill could be detected at night.